

Vehicle Inspection Report

Date Inspected: 24/04/2025 10:40

Reg: DN12AHX

VIN: W0L0SDL68C4187643

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	Hatchback	Doors	5
Model	CORSA SE - 1229cc	Fuel Type	Petrol	Colour	Grey
Mileage	115,169 miles	Transmission	Manual	Year of MFR	2012
		Gears	5	Date First Reg	30/06/2012

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Poor
Parcel Shelf	Yes
Odour	No
Comments	drivers seat torn

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bumper Rear

Dented

With Paint Damage

Repair and Refinish

Qtr Panel nsr

Boot Lid

Scratched

Over 25mm Not Thru Paint

Machine Polish

Qtr Panel nsr














Boot Lid

Chipped

1 To 5

Smart Repair

	Scratched Over 25mm Not Thru Paint Machine Polish	Chipped 1 To 5 Smart Repair		Door nsr Dented With Paint Damage Repair and Refinish
	Door nsf Chipped Multiple Chips Refinish	Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish		Wing nsf Chipped 1 To 5 Smart Repair
	Door Mirror Assy nsf Scratched (Painted) UpTo 25mm Thru Paint Smart Repair		Bonnet Chipped Multiple Chips Refinish	Bumper Front Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair		Wimper osf Chipped 1 To 5 Smart Repair	Wing osf Scratched Over 25mm Not Thru Paint Machine Polish
	Screen Front Chipped UpTo 10mm Smart Repair		Door osf Chipped Multiple Chips Refinish	Door osr Chipped Multiple Chips Refinish
	Qtr Panel osr Chipped 1 To 5 Smart Repair	Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish		Roof Scratched Over 25mm Not Thru Paint Machine Polish




Over 3mm

Replace

Damage Lines

Component	Condition	Severity	Repair
Bumper Rear	Dented	With Paint Damage	Repair and Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Chipped	Multiple Chips	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Chipped	Multiple Chips	Refinish
Door osr	Chipped	Multiple Chips	Refinish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish
Seat Base Cover osf	Torn	Over 3mm	Replace

Vehicle Splat



Splat Key

S2

Scratch/Paint defect 30-100mm

D3

Dent/damage 100mm +

C2

Multiple Chips

Comments

£100 ADDITIONAL FEE

noisy engine

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.