

Vehicle Inspection Report

Date Inspected: 31/03/2025 15:51

Reg: GN72PXH

VIN: JMZKF6WE690272996

NAMA Grading



Grade

1

Appraised By: Eastbourne Car Auctions

General Details

Make	MAZDA	Body Type	Estate	Doors	5
Model	CX-5 SPORT - 1998cc	Fuel Type	Petrol	Colour	Blue
Mileage	27028 miles	Transmission	Manual	Year of MFR	2022
		Gears	6	Date First Reg	01/09/2022

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Tools	No
OSR Depth	6 mm	Spare	No Spare
NSR Depth	6 mm		

Interior Condition




Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No	
History	
Stamps	


Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment			
	Bumper Rear Scratched Over 25mm Not Thru Paint Machine Polish	Door nsr Scratched Over 25mm Not Thru Paint Machine Polish	Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsf Scratched Over 25mm Not Thru Paint Machine Polish	Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish	 Bumper Front Moulding Broken Needs Replaced Replace
	Bumper Front Scratched Over 25mm Not Thru Paint Machine Polish	 Screen Front Chipped UpTo 10mm Smart Repair	Roof Scratched Over 25mm Not Thru Paint Machine Polish
	Door osf Dented 2 Or Less UpTo 10mm Smart Repair	 Sill Panel Trim os Scuffed (Unpainted) UpTo 100mm Smart Repair	

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front Moulding	Broken	Replace	Replace
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Sill Panel Trim os	Scuffed (Unpainted)	UpTo 100mm	Smart Repair

Vehicle Splat



Splat Key

D1

Dent/damage under 30mm

Comments

£65 ADDITIONAL FEE.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.