

### Vehicle Inspection Report

Date Inspected: 02/04/2025 18:35

**Reg:** LD63KPX

**VIN:** VF7SC8HR4DW639952

### NAMA Grading



Grade

**4**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	CITROEN	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	C3 VTR + HDI - 1398cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Silver
<b>Mileage</b>	58115 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2013
		<b>Gears</b>	5	<b>Date First Reg</b>	02/12/2013

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	1

### Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	6 mm	<b>Tools</b>	No
<b>NSR Depth</b>	2 mm	<b>Spare</b>	Steel

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service No**  
**History**  
**Stamps**

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	2	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

### Damage Assessment



#### Door osf

Chipped  
1 To 5  
Smart  
Repair



#### Door osr

Scratched  
Over  
25mm  
Thru Paint  
Refinish

#### Qtr Panel osr

Dented  
Between  
10mm +  
30mm  
Smart  
Repair

#### Door nsr

Dented  
2 Or Less  
UpTo



**Bumper Rear**

Poor Previous Repair

Paint Flake

Refinish



**Qtr Panel nsr**

Poor Previous Repair

Poor Paint Refinish

10mm

Smart Repair

**Door nsr**

Scratched

Over 25mm Not Thru Paint

Machine Polish



**Door nsf**

Scratched

UpTo 25mm Thru Paint

Smart Repair

**Door nsf**

Scratched

Over 25mm Not Thru Paint

Machine Polish



**Door nsf**

Chipped

1 To 5

Smart Repair



**Door Mirror Assy nsf**

Scratched (Painted)

Over 25mm Thru Paint

Smart Repair



**Wing nsf**

Poor Previous Repair

Poor Paint Refinish



**Bumper Front**

Poor Previous Repair

Poor Paint Refinish



**Bonnet**

Poor Previous Repair

Poor Paint Refinish

**Roof**

Dented

Over 2 UpTo 10mm

Smart Repair



**A Post ns**


Scratched

Over 25mm Not Thru Paint

Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Bumper Rear	Poor Previous Repair	Paint Flake	Refinish
Qtr Panel nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	UpTo 25mm Thru Paint	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Poor Previous Repair	Poor Paint	Refinish
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Bonnet	Poor Previous Repair	Poor Paint	Refinish
Roof	Dented	Over 2 UpTo 10mm	Smart Repair
A Post ns	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat



Splat Key

- S1**  
Scratch/Paint defect to 30mm
- S3**  
Scratch/Paint defect 100m +
- D1**  
Dent/damage under 30mm
- C2**  
Multiple Chips
- PP**  
Poor Previous

Comments

£65 ADDITIONAL FEE

service light is on the dash,engine fault message displays

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**