

Vehicle Inspection Report

Date Inspected: 02/04/2025 14:20

Reg: RK14TXY

VIN: WBA1A12020E696185

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	BMW	Body Type	Hatchback	Doors	5
Model	116I SPORT - 1598cc	Fuel Type	Petrol	Colour	Red
Mileage	107,612 miles	Transmission	Manual	Year of MFR	2014
		Gears	6	Date First Reg	01/03/2014

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



**Bumper Front**  
Scratched  
Over 100mm Thru Paint  
Refinish



**Bonnet**  
Chipped  
Multiple Chips  
Refinish



**Wing osf**  
Chipped  
1 To 5  
Smart Repair

**Wing osf**  
Scratched  
Over 25mm Not Thru Paint

**Door osf**  
Scratched  
Over 25mm Not Thru Paint

Machine  
Polish



**Screen  
Front**

Chipped

UpTo  
10mm

Smart  
Repair

Machine  
Polish



**Door osf**

Chipped

1 To 5

Smart  
Repair

**Door osr**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Door osr**

Chipped

1 To 5


Smart  
Repair

**Qtr Panel  
osr**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Qtr Panel  
osr**

Dented

Between  
10mm +  
30mm

Smart  
Repair



**Bumper  
Rear**

Poor  
Previous  
Repair

Poor Paint


Refinish

**Boot Lid**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Qtr Panel  
nsr**

Poor  
Previous  
Repair

Poor Paint

Refinish



**Door nsr**

Poor  
Previous  
Repair

Poor Paint

Refinish

**Door nsf**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Wing nsf**

Chipped

1 To 5

Smart  
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	Multiple Chips	Refinish
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
<p>£65 ADDITIONAL FEE.</p> <p>noisy engine</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>