

Vehicle Inspection Report

Date Inspected: 02/04/2025 13:23

Reg: GV71WSN

VIN: KMHKR81CRNU064319

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	HYUNDAI	Body Type	Estate	Doors	5
Model	IONIQ 5 ULTIMATE EV 4X4 - 0cc	Transmission	Auto	Colour	Green
Mileage	22,295 miles			Year of MFR	2022
				Date First Reg	12/02/2022

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	12/02/2026
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	3
OSR Depth	4 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Good
Parcel Shelf	No
Odour	No

Service History


Service History Stamps

Service Yes

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet

Chipped
1 To 5
Smart Repair

Bumper Front

Chipped
Multiple Chips
Smart Repair

Bumper Front

Scratched
Over 25mm Not Thru Paint
Machine Polish

Door osf

Scratched
Over 25mm Not



Screen Front
Chipped
UpTo 10mm
Smart Repair

Thru Paint
Machine Polish



Door osf
Chipped
1 To 5
Smart Repair

Door osr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door osr
Chipped
1 To 5
Smart Repair

Qtr Panel osr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Qtr Panel osr
Scratched
UpTo 25mm Thru Paint
Smart Repair




Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint
Smart Repair



Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart Repair

Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint
Smart Repair



Boot Lid
Scratched
UpTo 25mm Thru Paint
Smart Repair

Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish

Door nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsr
Chipped
1 To 5
Smart Repair


Door nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsf
Chipped
1 To 5
Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel Arch Extension os	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear Moulding	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Boot Lid	Scratched	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

S1
Scratch/Paint defect to 30mm

S2
Scratch/Paint defect 30-100mm

C2
Multiple Chips

Comments
£65 ADDITIONAL FEE. Charging cables missing. Last Service - 13/02/2025 at 21,130 miles (2 main dealer services)
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.