

### Vehicle Inspection Report

Date Inspected: 24/04/2025 14:14

**Reg:** EX65BFO

**VIN:** W0LPE9E30G1042551

### NAMA Grading



Grade

**4**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	VAUXHALL	<b>Body Type</b>	MPV	<b>Doors</b>	5
<b>Model</b>	ZAFIRA TOURER ELITE CDTIE - 1598cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Black
<b>Mileage</b>	155,128 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2016
		<b>Gears</b>	6	<b>Date First Reg</b>	18/01/2016

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	11/07/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	5 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	6 mm	<b>Tools</b>	No
<b>NSR Depth</b>	6 mm	<b>Spare</b>	No Spare

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service History Stamps**

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Leather	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	Yes	<b>Elec Windows</b>	4	<b>Heated Seats</b>	Yes
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	7	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	Yes

### Damage Assessment



#### Wing osf

Chipped  
1 To 5  
Smart Repair

#### Wing osf

Scratched  
Over 25mm Not Thru Paint  
Machine Polish












#### Door osf

Chipped  
1 To 5  
Smart Repair

#### Door osf

Scratched  
Over 25mm Not Thru Paint

	Machine Polish		<b>Door osr</b>  Dented  Over 30mm  Repair and Refinish		<b>Qtr Panel osr</b>  Scratched  Over 25mm Thru Paint  Refinish
	<b>Bumper Rear</b>  Scratched  Over 100mm Thru Paint  Refinish		<b>Tailgate</b>  Chipped  1 To 5  Smart Repair		<b>Qtr Panel nsr</b>  Dented  2 Or Less UpTo 10mm  Smart Repair
	<b>Qtr Panel nsr</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Door nsr</b>  Chipped  Multiple Chips  Refinish		<b>Door nsf</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish
	<b>Door Mirror Assy nsf</b>  Scratched (Painted)  UpTo 25mm Thru Paint  Smart Repair		<b>Wing nsf</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Wing nsf</b>  Dented  2 Or Less UpTo 10mm  Smart Repair
	<b>Door nsf</b>  Dented  2 Or Less UpTo 10mm  Smart Repair		<b>Bumper Front</b>  Chipped  Multiple Chips  Smart Repair		<b>Bonnet</b>  Chipped  Multiple Chips  Refinish
	<b>Screen Front</b>  Chipped  UpTo 10mm  Smart Repair		<b>Carpets Front</b>  Holed  Over 3mm  Replace		

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Tailgate	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	Multiple Chips	Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsf	Dented	2 Or Less UpTo 10mm	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	Multiple Chips	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Carpets Front	Holed	Over 3mm	Replace

Vehicle Splat

FRONT

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**D1**  
Dent/damage under 30mm

**D2**  
Dent/damage 30-100mm

**C1**  
Single Chip

**C2**  
Multiple Chips

Comments
Last Service - 24.03.2025 at 155127 miles (10 services)
eml light on Faulty Clutch
<b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b>