

Vehicle Inspection Report

Date Inspected: 02/04/2025 13:22

Reg: RJ17ZRZ

VIN: SHHFK6860HU008008

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	HONDA	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	CIVIC SR VTEC CVT - 988cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Grey
<b>Mileage</b>	56 786 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2017
				<b>Date First Reg</b>	30/06/2017

Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	1

Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	5 mm	<b>Tools Spare</b>	No
<b>NSR Depth</b>	5 mm		No Spare

Interior Condition

<b>Carpets</b>	Good
<b>Upholstery</b>	Good
<b>Seats</b>	Average
<b>Parcel Shelf</b>	No
<b>Odour</b>	No

Service History

Service No

History

Stamps

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	Yes

Damage Assessment



Bumper Front

Scratched

25 to 100mm Thru Paint

Smart Repair

Wing osf

Scratched

Over 25mm Not

Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bonnet

Chipped

1 To 5

Smart Repair

Door osf

Scratched

Over 25mm Not

Thru Paint  
Machine  
Polish



**Screen  
Front**  
  
Chipped  
  
UpTo  
10mm  
  
Smart  
Repair

Thru Paint  
Machine  
Polish



**Door osf**  
  
Chipped  
  
1 To 5  
  
Smart  
Repair

**Door osr**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door osr**  
  
Chipped  
  
1 To 5  
  
Smart  
Repair

**Qtr Panel  
osr**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
osr**  
  
Chipped  
  
1 To 5  
  
Smart  
Repair



**Bumper  
Rear**  
  
Scratched  
  
Over  
100mm  
Thru Paint  
  
Refinish

**Qtr Panel  
nsr**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
nsr**  
  
Dented  
  
Between  
10mm +  
30mm  
  
Smart  
Repair

**Door nsr**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Door nsf**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Wing nsf**  
  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

A top-down line drawing of a vehicle chassis. The drawing is oriented horizontally. The front of the vehicle is on the left, and the rear is on the right. The front end features a large rectangular grille with horizontal lines, four circular headlights, and a central rectangular bumper. The front left wheel is labeled 'C2'. The front right wheel is labeled 'C2'. The front center area is labeled 'C2'. The rear end features a large rectangular grille with horizontal lines, four circular headlights, and a central rectangular bumper. The rear left wheel is labeled 'C2'. The rear right wheel is labeled 'C2'. The rear center area is labeled 'C2'. The driver's side door is labeled 'D1'. The rear left side is labeled 'S3'. The rear right side is labeled 'S2'.

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

Comments
engine nunning rough. eml on
<b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b>