



VEHICLE INSPECTION REPORT

1FSA

Bentley Arnage Arnage RL [450] 4dr Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin
V5 Buyer To Apply

nama
GRADE
2

Details

Reg. date	05/02/2010	Body Style	Saloon	MOT Due	Expired
Year	2010	Keys	2	CAP Clean	£41,600.00
Mileage	9,545 Miles Warranted	Service history	Yes	CAP Average	£39,990.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	04/07/2018	Gears	6
VIN	SCBLC48F99CH14165	Last service miles	8,409	Doors	4

. Being sold on behalf of the High Court . Copy of last V5 .Registration number to be advised

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Cruise control
- Rear parking sensor
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Heated front seat
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- ABS
- Traction control
- Alloy wheels
- PAS
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Between 10mm + 30mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Wheel nsr
Scratched
Over 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

12: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

14: Wheel osr
Scratched
Over 50mm

No Image

15: Door osr
Scratched
Over 25mm Not Thru Paint

No Image


16: Door osf
Scratched
Over 25mm Not Thru Paint

No Image

17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK