

Vehicle Inspection Report

Date Inspected: 01/04/2025 15:51

Reg: WO64OXV

VIN: WBSFV920X0DX98246

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	BMW	Body Type	Saloon	Doors	4
Model	M5 AUTO - 4395cc	Fuel Type	Petrol	Colour	Blue
Mileage	96,306 miles	Transmission	Auto	Year of MFR	2015
				Date First Reg	27/02/2015

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	11/04/2025
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	Inflation Kit
		Tyre Comments	nsf tyre damage

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Poor
Parcel Shelf	No
Odour	No
Comments	front seats heavily worn and drivers door scuffed


Service History

Service History	Yes
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet
Chipped
1 To 5
Smart Repair



Bumper Front
Poor Previous Repair
Poor Paint Refinish








Screen Front
Chipped
UpTo 10mm
Smart Repair

Wing osf

Wing nsf

Door nsf

	Scratched	Scratched	Scratched
	Over 25mm Not Thru Paint	Over 25mm Not Thru Paint	Over 25mm Not Thru Paint
	Machine Polish	Machine Polish	Machine Polish
	Door nsr	Door nsr	Qtr Panel nsr
	Scratched	Chipped	Scratched
	Over 25mm Not Thru Paint	1 To 5	Over 25mm Not Thru Paint
	Machine Polish	Smart Repair	Machine Polish
	Bumper Rear	Bumper Rear	Qtr Panel osr
	Scratched	Scratched	Scratched
	25 to 100mm Thru Paint	Over 25mm Not Thru Paint	Over 25mm Not Thru Paint
	Smart Repair	Machine Polish	Machine Polish
	Door osr	Door osf	Wing osf
	Scratched	Scratched	Scratched
	Over 25mm Not Thru Paint	Over 25mm Not Thru Paint	Over 25mm Not Thru Paint
	Machine Polish	Machine Polish	Machine Polish
	Door osf	Door Pad osf	Wing nsf
	Dented	Scuffed	Dented
	Between 10mm + 30mm	Over 25mm	Between 10mm + 30mm
	Smart Repair	Smart Repair	Smart Repair
	Door Mirror Assy osf		
	Broken		
	Needs Replaced		
	Replace		

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Door Pad osf	Scuffed	Over 25mm	Smart Repair
Wing nsf	Dented	Between 10mm + 30mm	Smart Repair
Door Mirror Assy osf	Broken	Replace	Replace

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D1
Dent/damage under 30mm

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£65 ADDITIONAL FEE. Car has tracker fitted. Services stored in on-board system. Last Service - 14/03</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>