

### Vehicle Inspection Report

Date Inspected: 10/04/2025 08:22

**Reg:** EN59FBL

**VIN:** WVVZZZ6RZAU003914

### NAMA Grading



Grade

**3**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	VOLKSWAGEN	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	POLO MODA 60 - 1198cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Silver
<b>Mileage</b>	128,952 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2010
		<b>Gears</b>	5	<b>Date First Reg</b>	07/01/2010

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	4 mm	<b>Tools</b>	No
<b>NSR Depth</b>	4 mm	<b>Spare</b>	No Spare

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service No History Stamps**

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	No	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

### Damage Assessment



#### Bonnet

Chipped  
1 To 5  
Smart Repair



#### Bumper Front

Scratched  
25 to 100mm Thru Paint  
Smart Repair

#### Bumper Front

Scratched  
Over 25mm Not Thru Paint  
Machine Polish


#### Wing osf

Scratched  
Over 25mm Not

Thru Paint  
Machine  
Polish



**Wing osf**  
Dented  
Between  
10mm +  
30mm  
Smart  
Repair



**Screen  
Front**  
Chipped  
UpTo  
10mm  
Smart  
Repair

**Door osf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door osf**  
Chipped  
1 To 5  
Smart  
Repair

**Door osr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door osr**  
Chipped  
1 To 5  
Smart  
Repair

**Qtr Panel  
osr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Qtr Panel  
osr**  
Dented  
Between  
10mm +  
30mm  
Smart  
Repair



**Fuel Flap**  
Missing  
Needs  
Replaced  
Replace



**Bumper  
Rear**  
Poor  
Previous  
Repair  
Poor Paint  
Refinish

**Boot Lid**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Qtr Panel  
nsr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Qtr Panel  
nsr**  
Dented  
Between  
10mm +  
30mm  
Smart  
Repair

**Door nsr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door nsr**  
Chipped  
1 To 5  
Smart  
Repair


**Door nsf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door nsf**  
Chipped  
1 To 5  
Smart  
Repair



**Wing nsf**  
Scratched  
Over  
25mm  
Thru Paint



**Boot Lid**  
Scratched  
UpTo  
25mm  
Thru Paint



**Sill ns**  
Rusted  
Over 5mm  
Refinish


Refinish

Smart  
Repair

Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Dented	Between 10mm + 30mm	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Fuel Flap	Missing	Replace	Replace
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Boot Lid	Scratched	UpTo 25mm Thru Paint	Smart Repair
Sill ns	Rusted	Over 5mm	Refinish

Vehicle Splat



Splat Key

- S1**  
Scratch/Paint defect to 30mm
- S3**  
Scratch/Paint defect 100m +
- D1**  
Dent/damage under 30mm
- C2**  
Multiple Chips
- PP**  
Poor Previous
- R**  
Rust

## Comments

£65 ADDITIONAL FEE

boot doesnt open and noisy engine

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**