

Vehicle Inspection Report

Date Inspected: 03/04/2025 13:51

Reg: WJ07XYZ

VIN: YV1CZ714671339098

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLVO	Body Type	Estate	Doors	5
Model	XC90 SE D5 AUTO - 2401cc	Fuel Type	Diesel	Colour	Blue
Mileage	163,095 miles	Transmission	Auto	Year of MFR	2007
				Date First Reg	06/03/2007

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	26/02/2026
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need Refurb	4
OSR Depth	2 mm	Tools	No
NSR Depth	3 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History Stamps

Service Yes

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	7	Parking Sensors	Rear
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No


Damage Assessment

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Chipped

Edge Chip

Smart
Repair

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osr









Dented

2 Or Less
UpTo
10mm

Door osr

Scratched

Over
25mm Not
Thru Paint

	Smart Repair		Machine Polish		Qtr Panel osr Dented Between 10mm + 30mm Smart Repair
	Qtr Panel osr Scratched Up To 25mm Thru Paint Smart Repair		Bumper Rear Scratched Up To 25mm Thru Paint Smart Repair		Bumper Rear Scratched Over 25mm Not Thru Paint Machine Polish
	Tailgate Scratched Up To 25mm Thru Paint Smart Repair		Qtr Panel nsr Scratched Over 25mm Not Thru Paint Machine Polish		Door nsr Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsf Scratched Over 25mm Not Thru Paint Machine Polish		Door nsf Chipped 1 To 5 Smart Repair		Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Front Chipped Multiple Chips Smart Repair		Bonnet Chipped 1 To 5 Smart Repair		Screen Front Chipped Up To 10mm Smart Repair
	Lamp nsr Broken Needs Replaced Replace				

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	Edge Chip	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Qtr Panel osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Up To 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Tailgate	Scratched	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Lamp nsr	Broken	Replace	Replace

Vehicle Splat

Splat Key

S1
Scratch/Paint defect to 30mm

D1
Dent/damage under 30mm

C1
Single Chip

C2
Multiple Chips

X
Req Replacement

Comments
<p>Mileage of 1st service recorded incorrectly. Last Service - 23/01/2012 at 55,488 miles (5 main deale</p> <p>boot dont open</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>