



VEHICLE INSPECTION REPORT

GU61CZN

Ford Focus 1.6 EcoBoost Titanium X 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/09/2011	Keys	2	CAP Clean	£2,300.00
Year	2011	Service history	Yes	CAP Average	£1,875.00
Mileage	93,568 Miles Warranted	Service documents	Service Book	CAP Below	£1,475.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	White	Last service date	11/11/2022	Doors	5
VIN	WF0KXXGCBKBT77372	Last service miles	70,850		
Body Style	Hatchback	MOT Due	05/12/2025		

Last Service - 28.11.2022 at 70850 miles (5 main dealer services)

Clutch pedal stiff and low, nsf wheel looks bent, front end of car knocking when driving

Tyres

NSF	PETLAS	6.5mm
NSR	NEXEN	6.0mm
OSF	PETLAS	6.8mm
OSR	GT RADIAL	7.3mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- ESP
- Remote central locking
- Spare wheel
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Qtr Panel osr
Dented
Between 10mm + 30mm



3: Bumper Rear
Scratched
Over 100mm Thru Paint



4: Tailgate
Chipped
Over 5mm



5: Qtr Panel nsr
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Door nsf
Dented
Between 10mm + 30mm



8: Door Mirror Assy nsf
Broken
Replace




9: Wing nsf
Scratched
UpTo 25mm Thru Paint



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Roof
Chipped
Over 5mm



13: Wheel osf
Scratched
Over 50mm



14: Wheel osr
Scratched
Over 50mm



15: Wheel nsr
Scratched
Over 50mm



16: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK