

Vehicle Inspection Report

Date Inspected: 03/04/2025 13:20

Reg: HT18ADV

VIN: WF0WXXGCEWJU77956

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	FORD	Body Type	MPV	Doors	5
Model	GRAND C-MAX TITANIUM TURB - 999cc	Fuel Type	Petrol	Colour	Black
		Transmission	Manual	Year of MFR	2018
		Gears	6	Date First Reg	30/06/2018
Mileage	46322 miles				

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm		
NSR Depth	4 mm	Tools Spare	Yes Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No
Comments	one headrest missing

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	7	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	Yes



**Wing osf**  
Chipped  
1 To 5  
Smart  
Repair



**Door osf**  
Scratched  
Over  
25mm  
Thru Paint  
Refinish



**Door osr**  
Chipped  
1 To 5  
Smart  
Repair

**Door osr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Qtr Panel  
osr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Bumper  
Rear**  
Poor  
Previous  
Repair  
Paint  
Flake  
Refinish



**Bumper  
Rear**  
Insecure  
Action  
Required  
Smart  
Repair

**Qtr Panel  
nsr**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Door nsf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Wing nsf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Bumper  
Front**  
Scratched  
Over  
100mm  
Thru Paint  
Refinish

**Bonnet**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Roof**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish

**Door nsr**  
Poor  
Previous  
Repair  
Rippled  
Over 30%  
Repair  
and  
Refinish

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Poor Previous Repair	Paint Flake	Refinish
Bumper Rear	Insecure	Action Required	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Poor Previous Repair	Rippled Over 30%	Repair and Refinish

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
<div>eml light on</div> <div> No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on. </div>