



VEHICLE INSPECTION REPORT

VN59NZO

Skoda Octavia 2.0 TDI PD Laurin + Klement 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/10/2009	Keys	1	CAP Average	£500.00
Year	2009	Service history	Yes	CAP Below	£340.00
Mileage	115,463 Miles Warranted	Service documents	Printout	Gearbox	SEMI AUTO
Fuel Type	Diesel	Last service date	18/02/2015	Gears	6
Colour	BLUE	Last service miles	42,939	Doors	5
VIN	TMBAE61Z2A2022528	MOT Due	30/10/2025		
Body Style	Hatchback	CAP Clean	£700.00		

Last service 18/02/2015 @ 42939 miles (4 SERVICES) Gearbox Fault
Eml light is on

Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	4.0mm
OSF	SUNNY	5.0mm
OSR	AUTOGRIP	5.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Cruise control
- PAS
- Radio/CD
- Air conditioning
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Heated front seat
- Rear wiper
- Electric door mirrors

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Wheel nsr
Scratched
Over 50mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing osf
Chipped
1 To 5



6: Sill os
Rusted
Over 5mm



7: Door osf
Dented
2 Or Less UpTo 10mm



8: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



9: Door osf
Chipped
Edge Chip



10: Door osr
Dented
2 Or Less UpTo 10mm



11: Door Moulding osr
Scratched (Painted)
UpTo 25mm Thru Paint



12: Bumper Rear
Poor Previous Repair
Paint Flake



13: Tailgate
Dented
2 Or Less UpTo 10mm



14: Tailgate
Scratched
Over 25mm Not Thru Paint



15: Door nsr
Chipped
1 To 5



16: Door nsf
Chipped
1 To 5




17: Bumper Front
Poor Previous Repair
Paint Flake




18: Bonnet
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Dented
Over 2 UpTo 10mm



21: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		