

Vehicle Inspection Report

Date Inspected: 23/04/2025 15:51

Reg: LG67CVD

VIN: WF0EXXWPCEHG69307

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	FORD	Body Type	Hatchback	Doors	5
Model	MONDEO TITANIUM ECONETIC - 1499cc	Fuel Type	Diesel	Colour	Grey
Mileage	90,789 miles	Transmission	Manual	Year of MFR	2017
		Gears	6	Date First Reg	06/10/2017

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	3 mm	Alloys	Yes
NSF Depth	3 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	5 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No History Stamps

Extras


Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bumper Rear

Dented
With Paint Damage
Repair and Refinish



Reflector

Broken
Needs Replaced
Replace



Bumper Rear Moulding

Broken
Needs Replaced
Replace

Boot Lid

Scratched
Over 25mm Not

Thru Paint
Machine
Polish



**Qtr Panel
nsr**

Dented

With Paint
Damage

Repair
and
Refinish



Door nsr

Dented

With Paint
Damage

Repair
and
Refinish



Door nsf

Dented

With Paint
Damage

Repair
and
Refinish

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Chipped

1 To 5

Smart
Repair



Bonnet

Chipped

Multiple
Chips

Refinish



**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair



**Bumper
Front**

Scratched

Over
100mm
Thru Paint

Refinish



Wing osf

Dented

Over
30mm

Repair
and
Refinish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Chipped

1 To 5

Smart
Repair



Door osr

Dented

Over 30%
Of Panel

Replace



**Qtr Panel
osr**

Dented

With Paint
Damage

Repair
and
Refinish

Roof

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Dented	With Paint Damage	Repair and Refinish
Reflector	Broken	Replace	Replace
Bumper Rear Moulding	Broken	Replace	Replace
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Bonnet	Chipped	Multiple Chips	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing osf	Dented	Over 30mm	Repair and Refinish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Dented	Over 30% Of Panel	Replace
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

X
Req Replacement

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.