

### Vehicle Inspection Report

Date Inspected: 08/04/2025 13:28

**Reg:** GF65SNN

**VIN:** TMBKF75L1G6025371

### NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	SKODA	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	YETI OUTDOOR SE TSI - 1197cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Black
<b>Mileage</b>	159,264 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2015
		<b>Gears</b>	6	<b>Date First Reg</b>	31/10/2015

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	30/10/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	6 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	6 mm	<b>Tools</b>	No
<b>NSR Depth</b>	5 mm	<b>Spare</b>	Inflation Kit

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No
<b>Comments</b>	SEATS AND CARPETS STAINED

### Service History

<b>Service History</b>	Yes
<b>Stamps</b>	

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No



**Wing osf**  
Chipped  
1 To 5  
Smart  
Repair

**Wing osf**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door osf**  
Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish

**Door osr**  
Dented  
  
Over 2  
UpTo  
10mm  
  
Smart  
Repair



**Door osr**  
Chipped  
  
1 To 5  
  
Smart  
Repair

**Door osr**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
osr**  
Scratched  
  
UpTo  
25mm  
Thru Paint  
  
Smart  
Repair

**Qtr Panel  
osr**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Bumper  
Rear**  
Scratched  
  
Over  
100mm  
Thru Paint  
  
Refinish



**Bumper  
Rear  
Moulding**  
Scratched  
(Painted)  
  
Over  
25mm  
Thru Paint  
  
Smart  
Repair



**Tailgate**  
Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish



**Qtr Panel  
nsr**  
Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish



**Door nsr**  
Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish

**Door nsf**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door nsf**  
Scratched  
  
UpTo  
25mm  
Thru Paint  
  
Smart  
Repair



**Wing nsf**  
Dented  
  
Over  
30mm  
  
Repair  
and  
Refinish



**Bumper  
Front**  
Scratched  
  
Over  
100mm  
Thru Paint  
  
Refinish




**Bonnet**  
Chipped  
  
1 To 5  
  
Smart  
Repair

## Damage Lines

Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	Over 2 UpTo 10mm	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Bumper Rear Moulding	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Tailgate	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	UpTo 25mm Thru Paint	Smart Repair
Wing nsf	Dented	Over 30mm	Repair and Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair

## Vehicle Splat



## Splat Key

- S1**  
Scratch/Paint defect to 30mm
- S2**  
Scratch/Paint defect 30-100mm
- D1**  
Dent/damage under 30mm
- D2**  
Dent/damage 30-100mm
- D3**  
Dent/damage 100mm +
- C2**  
Multiple Chips

## Comments

intermittent eml £65 ADDITIONAL FEE Last Service - 14/02/2018 at 50,253 miles (2 MAIN DEALER SERVICES)

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**