

### Vehicle Inspection Report

Date Inspected: 07/04/2025 12:20

**Reg:** GX71OYJ

**VIN:** JSAMFH91S00227763

### NAMA Grading



Grade

**2**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	SUZUKI	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	IGNIS SZ3 DUALJET MHEV - 1197cc	<b>Fuel Type</b>	Hybrid	<b>Colour</b>	Green
<b>Mileage</b>	73617 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2021
		<b>Gears</b>	5	<b>Date First Reg</b>	17/09/2021

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	No
<b>NSF Depth</b>	5 mm	<b>Tools</b>	Yes
<b>OSR Depth</b>	6 mm	<b>Spare</b>	Inflation Kit
<b>NSR Depth</b>	6 mm		

### Interior Condition







<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History


**Service No**  
**History**  
**Stamps**

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	2	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

Damage Assessment					
	<b>Door osr</b> Chipped 1 To 5 Smart Repair		<b>Door nsr</b> Chipped 1 To 5 Smart Repair		<b>Bumper Front</b> Scratched 25 to 100mm Thru Paint Smart Repair
	<b>Bumper Front</b> Chipped Multiple Chips Smart Repair		<b>Bonnet</b> Chipped 1 To 5 Smart Repair		<b>Screen Front</b> Chipped UpTo 10mm Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Door osr	Chipped	1 To 5	Smart Repair
Door nsr	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair

Vehicle Splat	Splat Key
	<b>S2</b> Scratch/Paint defect 30-100mm <b>C1</b> Single Chip <b>C2</b> Multiple Chips

Comments
<p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>