

Vehicle Inspection Report

Date Inspected: 31/01/2025 12:43

Reg: GY17JNJ

VIN: WF0XXXTTGXHJ60551

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	FORD	Body Type	Van	Doors	5
Model	TRANSIT 350 - 1995cc	Fuel Type	Diesel	Colour	Silver
Mileage	4221 miles	Transmission	Manual	Year of MFR	2017
		Gears	6	Date First Reg	22/05/2017

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	No
NSF Depth	6 mm	Tools	No
OSR Depth	5 mm	Spare	No Spare
NSR Depth	6 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	3	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bonnet

Chipped
1 To 5
Smart
Repair

**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Front
Moulding**

Broken

Needs
Replaced

Replace

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsf

Chipped

1 To 5

Smart
Repair



Door nsr

Dented

Over
30mm

Repair
and
Refinish



Door nsr

Dented

Over
30mm

Repair
and
Refinish

Boot Lid

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Rear
Moulding**

Scuffed
(Unpainted)

Over
100mm

Smart
Repair



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



Door osf

Chipped

Edge Chip

Smart
Repair

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing osf

Chipped

1 To 5

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front Moulding	Broken	Replace	Replace
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Chipped	Edge Chip	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

- D3**
Dent/damage 100mm +
- C2**
Multiple Chips
- X**
Req Replacement
- SC**
Scuff

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.