

Vehicle Inspection Report

Date Inspected: 08/04/2025 09:48

Reg: OV06CUY

VIN: YV1SW494962589526

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLVO	Body Type	Estate	Doors	5
Model	V70 SE T AUTO - 1984cc	Fuel Type	Petrol	Colour	Black
Mileage	160,177 miles	Transmission	Auto	Year of MFR	2006
				Date First Reg	30/03/2006

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Poor
Seats	Average
Parcel Shelf	No
Odour	No
Comments	both front window switches broken. headlining damaged and drivers grab handle damaged

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	Yes

**Bonnet**

Poor
Previous
Repair

Paint
Flake

Refinish

**Bumper
Front**

Poor
Previous
Repair

Paint
Flake

Refinish

Wing osf

Scratched

Over
25mm Not
Thru Paint


Machine
Polish

**Wing osf**

Chipped

1 To 5

Smart
Repair

**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair

**Door osf**

Chipped

Multiple
Chips

Refinish

**Door osr**

Chipped

Multiple
Chips

Refinish

**Qtr Panel
osr**

Scratched

Over
25mm
Thru Paint

Refinish

**Bumper
Rear
Moulding**

Scratched
(Painted)

Over
25mm
Thru Paint

Smart
Repair

**Bumper
Rear**

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Boot Lid

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

**Qtr Panel
nsr**

Poor
Previous
Repair

Poor Paint

Refinish

**Door nsr**

Poor
Previous
Repair

Poor Paint

Refinish

**Door nsf**

Poor
Previous
Repair

Poor Paint


Refinish

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

**Wing nsf**

Chipped

1 To 5

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Poor Previous Repair	Paint Flake	Refinish
Bumper Front	Poor Previous Repair	Paint Flake	Refinish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Chipped	Multiple Chips	Refinish
Door osr	Chipped	Multiple Chips	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear Moulding	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsf	Poor Previous Repair	Poor Paint	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£65 ADDITIONAL FEE</p> <p>eml on and rear bumper misaligned</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>