

Vehicle Inspection Report

Date Inspected: 11/04/2025 12:51

Reg: KM21XNR

VIN: VR7BAHNSAME011341

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	CITROEN	Body Type	Hatchback	Doors	5
Model	C4 SENSE + PURETECH S/S - 1200cc	Fuel Type	Petrol	Colour	Grey
		Transmission	Manual	Year of MFR	2021
Mileage	33,513 miles	Gears	6	Date First Reg	31/03/2021

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	26/02/2026
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	3
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition


Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service Yes
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bonnet

Chipped
1 To 5
Smart
Repair

**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Front**

Chipped

Multiple
Chips

Smart
Repair

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsr

Dented

2 Or Less
UpTo
10mm

Smart
Repair

**Bumper
Rear**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Rear**

Chipped

Multiple
Chips

Smart
Repair

**Qtr Panel
osr**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing osf

Chipped

1 To 5

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

D1
Dent/damage under 30mm

C2
Multiple Chips

Comments
<p>£100 ADDITIONAL FEE Last Service - 28/02/2024 at 28,009 miles (1 MAIN DEALER SERVICE)</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>