

Vehicle Inspection Report

Date Inspected: 11/04/2025 10:43

Reg: GX72KTV

VIN: JMZKF6W7A90273361



Appraised By: Eastbourne Car Auctions

General Detai	ls					Miscella	aneous
	5 SPORT BLACK FION - 1998cc	Body Type Fuel Type Transmission	Esta Petro Auto		5 Red 2022 01/09/20	V5 Loc No. Ke	
Tyres & Whee	Is			Interior Condi	tion	Service	History
OSF Depth NSF Depth OSR Depth NSR Depth	5 mm 4 mm 4 mm 5 mm	Alloys Alloys That Need Refurb Tools Spare	Yes 3 No No Spar	Carpets Upholstery Seats Parcel Shelf Odour	Averaç Averaç Averaç No No	ge Histo	-
Extras							
Metallic Pain	nt Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Condition	-	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entr	-	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment







Bonnet Chipped 1 To 5 Smart Repair

Bumper

Scratched

25mm Not

Thru Paint

Machine

Door nsr

Chipped

1 To 5

Smart

Repair

Wing nsf

Chipped

1 To 5

Smart

Repair

Polish

Rear

Over



Qtr Panel nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper Front Scratched

Over 25mm Not Thru Paint

Machine

Screen

Chipped

Front

UpTo

10mm

Smart

Repair

Polish





Door nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Wing nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper

Front Chipped

Multiple Chips

Smart Repair

Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door osr


Scratched

Over 25mm Not Thru Paint

Machine Polish

Damage Lines

Component	Condition	Severity	Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish



Splat Key

Multiple Chips

Comments

£65 ADDITIONAL FEE

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.