

Vehicle Inspection Report

Date Inspected: 15/04/2025 11:24

Reg: LF21PMX

VIN: SJNFFAJ11U2946281



Appraised By: Eastbourne Car Auctions

General Details							Miscellaneous	
	AI N-MOTION 1332cc iiles	Body Type Fuel Type Transmission	Hatchba Petrol Auto			V5 Loc No. Ke		
Tyres & Wheels				Interior Condi	tion	Service	History	
OSF Depth NSF Depth OSR Depth NSR Depth	4 mm 2 mm 5 mm 5 mm	Alloys Alloys That Need Refurb Tools Spare	Yes 4 No Inflatio Kit	Carpets Upholstery Seats Parcel Shelf Odour	Averaç Averaç Averaç Yes No	ge Histo	Service No History Stamps	
Extras								
Metallic Paint Air Conditioning Stereo Keyless Entry Phone Kit	Yes Yes Radio Yes Yes	Central Locking Sun Roof Sat Nav Towbar Drv Airbag	Yes Yes Built In No Yes	Interior Elec Windows Cruise Number of Seats Reversing Camera	Leather 4 Yes 5 Yes	Electric Seats Heated Seats Xenons Parking Sensors EML	Yes Yes No Front & Rear No	

Damage Assessment



Door osf Chipped Edge Chip Smart

Repair



Bumper Rear

Scratched

25 to 100mm Thru Paint

Smart Repair

Bonnet

Scratched Over 25mm Not Thru Paint

Machine Polish



Qtr Panel nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish



Wing nsf Dented Over 30mm

Repair and Refinish

Damage Lines

Component					
Door osf					
Bumper Rear					
Qtr Panel nsr					
Wing nsf					
Bonnet					

Condition Chipped Scratched Scratched Dented Scratched

Severity Edge Chip 25 to 100mm Thru Paint Over 25mm Not Thru Paint Over 30mm Over 25mm Not Thru Paint

Repair

Smart Repair Smart Repair Machine Polish Repair and Refinish Machine Polish

S2 D2 FRONT

Splat Key

Scratch/Paint defect 30-100mm Dent/damage 30-100mm

Vehicle Splat

Comments

£100 ADDITIONAL FEE. EXPIRED MOT.

gearbox fault squeaky brakes

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.