

Vehicle Inspection Report

Date Inspected: 11/04/2025 11:00

Reg: LT70KDJ

VIN: KNAD6811VL6459314

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	KIA	Body Type	Hatchback	Doors	5
Model	STONIC 3 ISG S-A - 998cc	Fuel Type	Petrol	Colour	Grey
Mileage	63,822 miles	Transmission	Auto	Year of MFR	2020
				Date First Reg	01/09/2020

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	31/08/2025
No. Keys	2

Tyres & Wheels

OSF Depth	3 mm	Alloys	Yes
NSF Depth	2 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	3 mm	Spare	Inflation Kit

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History Stamps

Service Yes

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Bonnet
Chipped
1 To 5
Smart Repair



Screen Front
Chipped
UpTo 10mm
Smart Repair

Wing osf
Scratched
Over 25mm Not Thru Paint
Machine Polish

Door osf
Scratched
Over 25mm Not Thru Paint
Machine Polish

Door osr
Scratched
Over 25mm Not Thru Paint
Machine Polish

Bumper Rear
Scratched
Over 25mm Not Thru Paint
Machine Polish

Bumper Rear
Chipped
Multiple Chips
Smart Repair

Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsr
Chipped
1 To 5
Smart Repair

Door nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsf
Chipped
1 To 5
Smart Repair

Wing nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

A top-down line drawing of a car. The car is oriented horizontally. There are four wheels, each represented by a circle with a smaller circle inside. The car body is outlined with a thick line. The front of the car is on the right, and the rear is on the left. The driver's side is on the left, and the passenger side is on the right. There are labels 'C2' in red text located in the following positions: one on the left side of the rear door, one in the center of the rear seat, one in the center of the front seat, one on the right side of the front door, and one on the right side of the front door. There is a label 'S3' in red text located on the right side of the front door.

Splat Key

S3
Scratch/Paint defect 100m +

C2
Multiple Chips

Comments

£65 ADDITIONAL FEE. Last Service - 14/01/2025 at 61,655 miles (1 main dealer service)

engine noisy

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.