

Vehicle Inspection Report

Date Inspected: 30/01/2025 10:56

Reg: VE67XRF

VIN: JMZKF6W1600666056

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	MAZDA	Body Type	Estate	Doors	5
Model	CX-5 SPORT NAV D - 2191cc	Fuel Type	Diesel	Colour	Red
Mileage	84761 miles	Transmission	Manual	Year of MFR	2018
		Gears	6	Date First Reg	07/02/2018

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	6 mm	Spare	Inflation Kit

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	No	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	Yes



Door Mirror Assy osf

Scratched (Painted)

UpTo 25mm Thru Paint

Smart Repair

Qtr Panel osr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Front

Scratched

25 to 100mm Thru Paint

Smart Repair

Door osf

Chipped

Edge Chip

Smart Repair

Door osr

Chipped

Edge Chip

Smart Repair

Door nsf

Chipped

Edge Chip

Smart Repair

Bonnet

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper Rear

Scratched

25 to 100mm Thru Paint

Smart Repair

Wing nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Screen Front

Chipped

UpTo 10mm

Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Door Mirror Assy osf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Door osf	Chipped	Edge Chip	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	Edge Chip	Smart Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	Edge Chip	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE</p> <p>engine noisy,eml light on</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>