



Vehicle Inspection Report

Date Inspected: 10/04/2025 09:43

Reg: LD60KGZ

WMWZF32030TY73855 VIN:

NAMA Grading



Grade

Appraised By: Eastbourne Car Auctions

General Details

Make MINI Model

COOPER CLUBMAN -1598cc

Mileage 122,187 miles

Body Type

Fuel Type Transmission

Alloys That Need

Gears

Estate

Petrol

Manual

Doors Colour

Year of MFR

Date First Reg

Brown 2010

5

24/09/2010

Miscellaneous

V5 Location

No. Keys

Tyres & Wheels

OSF Depth 4 mm **NSF** Depth

4 mm **OSR Depth** 4 mm

NSR Depth

4 mm

Tools

Spare

Alloys

Refurb

No No

Spare

Yes

4

Interior Condition

Carpets Upholstery

Seats

Average Average

Average

Parcel Shelf No Odour No Service History

Service No History **Stamps**

Extras

Metallic Paint

Air Conditioning Stereo

Keyless Entry Phone Kit

Yes

Central Locking Sun Roof

Yes Sat Nav Radio

No **Towbar**

Drv Airbag No

Interior Yes

Elec Windows No

Cruise No No

Number of Seats Reversing Camera Yes

Electric Seats Cloth

No

2 **Heated Seats** No Xenons

5 **Parking Sensors**

> **EML** No

Damage Assessment



Bonnet

Chipped Multiple Chips

Refinish



Bumper **Front**

Scratched

Over 100mm Thru Paint

Refinish



Screen Front

No

No

No

No

Chipped

UpTo 10mm

Smart Repair

Wing osf

Scratched

Over 25mm Not Thru Paint

Machine Polish



Wing osf Chipped 1 To 5 Smart Repair



Dented With Paint Damage

Door osf

Repair and Refinish

Door osr

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door osr

Chipped

1 To 5

Smart Repair



Qtr Panel osr

Scratched

Over 25mm Thru Paint

Refinish

Roof

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Rear

Scratched

Over 100mm Thru Paint

Refinish



Boot Lid

Chipped

Multiple Chips

Refinish



Bumper Rear Moulding

Broken

Needs Replaced

Replace



Scratched

Over 25mm Not Thru Paint

Machine Polish



Qtr Panel nsr

Chipped

1 To 5 Smart Repair



Door nsf

Chipped

Multiple Chips

Refinish



Wing nsf

Chipped

1 To 5

Smart Repair



Reflector

Broken

Needs Replaced

Replace



Qtr Panel nsr

Dented

With Paint Damage

Repair and Refinish



Door osr

Dented

2 Or Less UpTo 10mm

Smart Repair



Qtr Panel osr


Dented

2 Or Less UpTo 10mm

Smart Repair

Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Chipped	Multiple Chips	Refinish
Bumper Rear Moulding	Broken	Replace	Replace
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsf	Chipped	Multiple Chips	Refinish
Wing nsf	Chipped	1 To 5	Smart Repair
Reflector	Broken	Replace	Replace
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Dented	2 Or Less UpTo 10mm	Smart Repair



Splat Key

S3

Scratch/Paint defect 100m +

D3

Dent/damage 100mm +

C2

Multiple Chips

Comments

noisy engine and bonnet doesnt release

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.