

Vehicle Inspection Report

Date Inspected: 25/04/2025 10:45

Reg: ND55NFH

VIN: VF33CNFUL84500312

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	PEUGEOT	Body Type	Hatchback	Doors	5
Model	307 S - 1587cc	Fuel Type	Petrol	Colour	Blue
Mileage	129,654 miles	Transmission	Manual	Year of MFR	2005
		Gears	5	Date First Reg	28/12/2005

Miscellaneous

V5 Location	
No. Keys	3

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need	4
OSR Depth	4 mm	Refurb	
NSR Depth	4 mm	Tools	Yes
		Spare	Steel

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No  
History  
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No




**Bumper Front**  
Scratched  
Over 100mm Thru Paint  
Refinish



**Bonnet**  
Chipped  
1 To 5  
Smart Repair



**Wing osf**  
Chipped  
1 To 5  
Smart Repair



**Screen Front**  
Chipped  
UpTo 10mm  
Smart Repair



**Door osf**  
Dented  
With Paint Damage  
Repair and Refinish



**Door osr**  
Dented  
With Paint Damage  
Repair and Refinish




**Qtr Panel osr**  
Dented  
With Paint Damage  
Repair and Refinish



**Bumper Rear**  
Poor Previous Repair  
Rippled UpTo 30%  
Repair and Refinish



**Boot Lid**  
Dented  
2 Or Less UpTo 10mm  
Smart Repair



**Qtr Panel nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Door nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Door nsf**  
Dented  
With Paint Damage  
Repair and Refinish



**Door Mirror Assy nsf**  
Scratched (Painted)  
Over 25mm Thru Paint  
Smart Repair



**Wing nsf**  
Scratched  
Over 25mm Thru Paint  
Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear	Poor Previous Repair	Rippled UpTo 30%	Repair and Refinish
Boot Lid	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish

[illegible]

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**D2**  
Dent/damage 30-100mm

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments

passenger window fault only on drivers switch

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

passenger window fault only on drivers switch

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.