

### Vehicle Inspection Report

Date Inspected: 22/04/2025 12:24

**Reg:** LP11NAA

**VIN:** MA3GFC31S00444286

### NAMA Grading



Grade

**5**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	SUZUKI	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	ALTO SZ2 - 996cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Black
<b>Mileage</b>	85,707 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2011
		<b>Gears</b>	5	<b>Date First Reg</b>	29/07/2011

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	1

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	No
<b>NSF Depth</b>	4 mm	<b>Tools</b>	No
<b>OSR Depth</b>	4 mm	<b>Spare</b>	Space Saver
<b>NSR Depth</b>	4 mm		

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Poor
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

<b>Service No</b>	
<b>History</b>	
<b>Stamps</b>	

### Extras

<b>Metallic Paint</b>	No	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	No	<b>Sun Roof</b>	No	<b>Elec Windows</b>	2	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	4	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	No	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No



**Bumper Front**  
Poor Previous Repair  
Poor Paint Refinish



**Bonnet**  
Chipped  
1 To 5  
Smart Repair



**Screen Front**  
Chipped  
UpTo 10mm  
Smart Repair



**Wing osf**  
Poor Previous Repair  
Poor Paint Refinish



**Door osf**  
Poor Previous Repair  
Poor Paint Refinish



**Door osr**  
Poor Previous Repair  
Poor Paint Refinish



**Qtr Panel osr**  
Poor Previous Repair  
Poor Paint Refinish



**Bumper Rear**  
Cracked  
Over 25mm  
Replace



**Boot Lid**  
Dented  
2 Or Less UpTo 10mm  
Smart Repair



**Qtr Panel nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Door nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Door nsf**  
Dented  
With Paint Damage  
Repair and Refinish



**Wing nsf**  
Dented  
2 Or Less UpTo 10mm  
Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Poor Previous Repair	Poor Paint	Refinish
Door osf	Poor Previous Repair	Poor Paint	Refinish
Door osr	Poor Previous Repair	Poor Paint	Refinish
Qtr Panel osr	Poor Previous Repair	Poor Paint	Refinish
Bumper Rear	Cracked	Over 25mm	Replace
Boot Lid	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Dented	2 Or Less UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

**D1**  
Dent/damage under 30mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

**PP**  
Poor Previous

**X**  
Req Replacement

Comments
<p>rear wiper broken and engine noisy</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>