

Vehicle Inspection Report

Date Inspected: 15/04/2025 09:58

Reg: HY69RJZ

VIN: SJNFAAJ11U2582811

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	NISSAN	Body Type	Hatchback	Doors	5
Model	QASHQAI TEKNA + DCI S-A - 1461cc	Fuel Type	Diesel	Colour	White
Mileage	74092 miles	Transmission	Auto	Year of MFR	2019
				Date First Reg	30/09/2019

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	4 mm	Spare	Inflation Kit

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No



Door osf
Chipped
Edge Chip
Smart
Repair



Door osr
Chipped
Edge Chip
Smart
Repair

Bumper Rear
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Tailgate
Scratched

Over
25mm
Thru Paint
Refinish



Door nsr
Scratched

Over
25mm
Thru Paint
Refinish

Door nsf
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door Mirror Assy nsf
Scratched
(Painted)

Over
25mm
Thru Paint
Smart
Repair

Wing nsf
Scratched

Over
25mm Not
Thru Paint
Machine
Polish



Bumper Front
Chipped

1 To 5
Smart
Repair



Bonnet
Chipped

1 To 5
Smart
Repair



Screen Front
Chipped

UpTo
10mm
Smart
Repair



Seat Base Cover osf
Torn

Over 3mm
Replace



Bonnet
Dented

2 Or Less
UpTo
10mm
Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	Edge Chip	Smart Repair
Door osr	Chipped	Edge Chip	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Tailgate	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	1 To 5	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Seat Base Cover osf	Torn	Over 3mm	Replace
Bonnet	Dented	2 Or Less UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

C2
Multiple Chips

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.