

Vehicle Inspection Report

Date Inspected: 11/04/2025 18:27

Reg: CP69EKO

VIN: MMCXTA03AKH034882

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	mitsubishi	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	MIRAGE 4 CVT - 1193cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Black
<b>Mileage</b>	17,752 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2019
				<b>Date First Reg</b>	20/12/2019

Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	5 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	4 mm	<b>Tools Spare</b>	No Inflation Kit
<b>NSR Depth</b>	4 mm		

Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

Service History

Service No History Stamps

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

Damage Assessment



Bonnet

Chipped  
1 To 5  
Smart Repair

Bumper Front

Scratched  
Over 25mm Not Thru Paint  
Machine Polish



Bumper Front


Chipped  
Multiple Chips  
Smart Repair

Door osf

Scratched  
Over 25mm Not



**Wing osf**  
Chipped  
Multiple  
Chips  
Refinish



**Screen  
Front**  
Chipped  
  
UpTo  
10mm  
  
Smart  
Repair

Thru Paint  
  
Machine  
Polish



**Door osf**  
Chipped  
  
1 To 5  
  
Smart  
Repair

**Door osr**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door osr**  
Chipped  
  
1 To 5  
  
Smart  
Repair



**Qtr Panel  
osr**  
Scratched  
  
Over  
25mm  
Thru Paint  
Refinish



**Bumper  
Rear**  
Poor  
Previous  
Repair  
  
Paint  
Flake  
Refinish

**Boot Lid**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
nsr**  
Scratched  
  
Over  
25mm  
Thru Paint  
Refinish



**Door nsr**  
Chipped  
  
Multiple  
Chips  
Refinish

**Door nsf**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door nsf**  
Chipped  
  
1 To 5  
  
Smart  
Repair

**Wing nsf**  
Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Wing nsf**  
Chipped  
  
1 To 5  
  
Smart  
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Chipped	Multiple Chips	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear	Poor Previous Repair	Paint Flake	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Chipped	Multiple Chips	Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair

Vehicle Splat

S3

PP

C2

C2

C2

C2

C2

C2

S2

PP

C2

C2

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**S3**  
Scratch/Paint defect 100m +

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**