

Vehicle Inspection Report

Date Inspected: 12/02/2025 16:51

Reg: LD16UEF

VIN: 6FPPXXMJ2PGA57958

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	FORD	<b>Fuel Type</b>	Diesel	<b>Doors</b>	5
<b>Model</b>	RANGER XLT 4X4 DCB TDCI - 2198cc	<b>Transmission</b>	Manual	<b>Colour</b>	Red
<b>Mileage</b>	102502 miles	<b>Gears</b>	6	<b>Year of MFR</b>	2016
				<b>Date First Reg</b>	07/07/2016

Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	6 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	6 mm	<b>Tools</b>	No
<b>OSR Depth</b>	5 mm	<b>Spare</b>	No Spare
<b>NSR Depth</b>	5 mm		

Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	No
<b>Odour</b>	No

Service History

<b>Service No</b>	
<b>History</b>	
<b>Stamps</b>	


Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	Yes	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

Damage Assessment


Wing osf

Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



Wing osf

Chipped  
1 To 5  
Smart  
Repair




Door osf

Scratched  
Over  
25mm  
Thru Paint  
Refinish

Door osr

Scratched  
Over  
25mm Not  
Thru Paint



Door osr

Chipped  
Edge Chip  
Smart  
Repair



C Post os

Dented  
With Paint  
Damage  
Repair



**Roof**

Poor  
Previous  
Repair  
  
Paint  
Flake  
  
Refinish



**Qtr Panel  
osr**

Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish



**Tailgate**

Dented  
  
Over  
30mm  
  
Repair  
and  
Refinish

**Qtr Panel  
nsr**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door nsr**

Scratched  
  
Over  
25mm  
Thru Paint  
  
Refinish

**Door nsf**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Door nsf**

Chipped  
  
Edge Chip  
  
Smart  
Repair



**Door  
Mirror  
Assy nsf**

Scratched  
(Painted)  
  
UpTo  
25mm  
Thru Paint  
  
Smart  
Repair



**Wing nsf**

Scratched  
  
Over  
25mm  
Thru Paint  
  
Refinish



**Bumper  
Front**

Scratched  
  
Over  
100mm  
Thru Paint  
  
Refinish



**Bonnet**

Chipped  
  
1 To 5  
  
Smart  
Repair

**Screen  
Front**

Chipped  
  
UpTo  
10mm  
  
Smart  
Repair

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	Edge Chip	Smart Repair
C Post os	Dented	With Paint Damage	Repair and Refinish
Roof	Poor Previous Repair	Paint Flake	Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Tailgate	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	Edge Chip	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

- S2**  
Scratch/Paint defect 30-100mm
- S3**  
Scratch/Paint defect 100m +
- D3**  
Dent/damage 100mm +
- C1**  
Single Chip
- C2**  
Multiple Chips
- PP**  
Poor Previous

Comments
front bumper out of line
<b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b>