

Vehicle Inspection Report

Date Inspected: 22/04/2025 17:03

Reg: GF16GOJ

VIN: W0LDD6E76GC600723

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	Hatchback	Doors	5
Model	VIVA SE AC - 999cc	Fuel Type	Petrol	Colour	Red
Mileage	99,857 miles	Transmission	Manual	Year of MFR	2016
		Gears	5	Date First Reg	21/03/2016

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	No
NSF Depth	4 mm	Tools	No
OSR Depth	4 mm	Spare	No Spare
NSR Depth	4 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	Yes



Bonnet

Chipped
Multiple
Chips
Refinish



Wing osf

Chipped
1 To 5
Smart
Repair



Door osr

Chipped
1 To 5
Smart
Repair



**Bumper
Rear**

Chipped
Multiple
Chips
Smart
Repair

Door nsf

Chipped
1 To 5
Smart
Repair




**Screen
Front**

Chipped
UpTo
10mm
Smart
Repair



**Qtr Panel
osr**

Chipped
1 To 5
Smart
Repair



**Qtr Panel
nsr**

Chipped
1 To 5
Smart
Repair




**Bumper
Front**

Scratched
25 to
100mm
Thru Paint
Smart
Repair



Door osf

Chipped
1 To 5
Smart
Repair



Door nsr

Chipped
1 To 5
Smart
Repair

**Bumper
Rear**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Chipped	1 To 5	Smart Repair

[illegible]

Splat Key

S2
Scratch/Paint defect 30-100mm

C2
Multiple Chips

Comments

£65 ADDITIONAL FEE

eml on

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.