

Vehicle Inspection Report

Date Inspected: 17/04/2025 09:17

Reg: EN16LGW

VIN: UU17SDCJ555719312

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	DACIA	Body Type	Estate	Doors	5
Model	LOGAN MCV LAUREATE DCI - 1461cc	Fuel Type	Diesel	Colour	White
		Transmission	Manual	Year of MFR	2016
Mileage	88,069 miles	Gears	5	Date First Reg	15/06/2016

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	15/06/2025
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	6 mm	Tools	No
NSR Depth	5 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bonnet

Dented

Over
30mm

Repair
and
Refinish

Bumper
Front

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper
Front

Scratched

25 to
100mm
Thru Paint

Smart
Repair



Wing nsf
Dented
Over 30mm
Repair and Refinish



Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint
Smart Repair



Screen Front
Chipped
UpTo 10mm
Smart Repair

Door nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsf
Chipped
1 To 5
Smart Repair

Door nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish

Door nsr
Chipped
1 To 5
Smart Repair

Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Qtr Panel nsr
Dented
2 Or Less UpTo 10mm
Smart Repair



Bumper Rear
Poor Previous Repair
Rippled UpTo 30%
Repair and Refinish



Boot Lid
Dented
With Paint Damage
Repair and Refinish

Qtr Panel osr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Qtr Panel osr
Dented
2 Or Less UpTo 10mm
Smart Repair



Door osr
Chipped
1 To 5
Smart Repair



Door osf
Dented
2 Or Less UpTo 10mm
Smart Repair



Wing osf
Chipped
1 To 5
Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Dented	Over 30mm	Repair and Refinish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing nsf	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Bumper Rear	Poor Previous Repair	Rippled UpTo 30%	Repair and Refinish
Boot Lid	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Door osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D1
Dent/damage under 30mm

D3
Dent/damage 100mm +

C2
Multiple Chips

PP
Poor Previous

Comments
<p>Last Service - 23/05/2024 at 81,515 miles (8 SERVICES (3 MAIN DEALER))</p> <p>engine runnig rough and burning smell</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>