

### Vehicle Inspection Report

Date Inspected: 14/04/2025 15:39

**Reg:** GF60RZC

**VIN:** SALFA2AE6BH229020

### NAMA Grading



Grade

**2**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	LAND ROVER	<b>Body Type</b>	Estate	<b>Doors</b>	5
<b>Model</b>	FREELANDER HSE SD4 AUTO - 2179cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	White
<b>Mileage</b>	157,856 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2010
				<b>Date First Reg</b>	15/12/2010

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	22/12/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	6 mm	<b>Tools</b>	Yes
<b>NSR Depth</b>	6 mm	<b>Spare</b>	Alloy

### Interior Condition





<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service History**  
Stamps


### Extras

<b>Metallic Paint</b>	No	<b>Central Locking</b>	Yes	<b>Interior</b>	Leather	<b>Electric Seats</b>	Yes
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	Yes	<b>Elec Windows</b>	4	<b>Heated Seats</b>	Yes
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

Damage Assessment					
	<b>Door osr</b>		<b>Bumper Rear</b>		<b>Qtr Panel nsr</b>
	Chipped		Scratched		Scratched
	1 To 5		Over 25mm Not Thru Paint		Over 25mm Thru Paint
	Smart Repair		Machine Polish		Refinish
	<b>Door Mirror Assy nsf</b>		<b>Bumper Front</b>		<b>Bonnet</b>
	Scratched (Painted)		Chipped		Chipped
	Over 25mm Not Thru Paint		Multiple Chips		1 To 5
	Machine Polish		Smart Repair		Smart Repair
	<b>Screen Front</b>				
	Chipped				
	UpTo 10mm				
	Smart Repair				

Damage Lines			
Component	Condition	Severity	Repair
Door osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair

## Vehicle Splat



## Splat Key

### S2

Scratch/Paint defect 30-100mm

### C2

Multiple Chips

## Comments

Last Service - 20/03/2019 at 110,854 miles (8 services (6 main dealer))

reduced engine power sometimes displays on dash,engine hunting

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**