

### Vehicle Inspection Report

Date Inspected: 16/04/2025 15:53

**Reg:** GU71UFN

**VIN:** JTDKBABB40A006515

### NAMA Grading



Grade

**3**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	TOYOTA	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	YARIS CROSS ICON HEV AUTO - 1490cc	<b>Fuel Type</b>	Hybrid	<b>Colour</b>	Blue
<b>Mileage</b>	19430 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2021
				<b>Date First Reg</b>	08/10/2021

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	3 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	3 mm	<b>Tools</b>	No
<b>OSR Depth</b>	4 mm	<b>Spare</b>	No Spare
<b>NSR Depth</b>	6 mm		

### Interior Condition



<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History


**Service No**  
**History**  
**Stamps**

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

Damage Assessment					
	<b>Door osf</b> Chipped Edge Chip Smart Repair		<b>Bumper Rear</b> Poor Previous Repair Poor Paint Refinish		<b>Qtr Panel nsr</b> Scratched Over 25mm Not Thru Paint Machine Polish
	<b>Door nsr</b> Scratched Over 25mm Not Thru Paint Machine Polish		<b>Wing nsf</b> Scratched Over 25mm Not Thru Paint Machine Polish		<b>Bumper Front</b> Scratched Over 100mm Thru Paint Refinish
	<b>Screen Front</b> Chipped UpTo 10mm Smart Repair				

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	Edge Chip	Smart Repair
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair



Splat Key
<b>S2</b> Scratch/Paint defect 30-100mm
<b>C2</b> Multiple Chips
<b>PP</b> Poor Previous

Comments
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.