

Vehicle Inspection Report

Date Inspected: 24/04/2025 13:08

Reg: GN13ZXM

VIN: TMBZZZAAZDD635886

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	SKODA	Body Type	Hatchback	Doors	5
Model	CITIGO SE 12V - 999cc	Fuel Type	Petrol	Colour	Green
Mileage	122,556 miles	Transmission	Manual	Year of MFR	2013
		Gears	5	Date First Reg	12/03/2013

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	20/10/2025
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	No
NSF Depth	4 mm	Tools	No
OSR Depth	4 mm	Spare	No Spare
NSR Depth	4 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service

Yes


History

Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bonnet

Dented

With Paint Damage

Repair and Refinish



Bumper Front

Scratched

Over 100mm Thru Paint

Refinish



Wing osf

Dented

Between 10mm + 30mm

Smart Repair



Screen Front

Chipped

UpTo 10mm

Door osf

Scratched

Over 25mm Not Thru Paint



Door osr

Dented

Over 30mm

Repair



**Qtr Panel
osr**

Dented
2 Or Less
UpTo
10mm

Smart
Repair



Boot Lid

Chipped
1 To 5

Smart
Repair



**Badgedecal
Rear**

Missing

Needs
Replaced

Replace



**Bumper
Rear**

Scratched

Over
100mm
Thru Paint

Refinish



**Qtr Panel
nsr**

Dented

Between
10mm +
30mm

Smart
Repair



Door nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsf

Dented

Over
30mm

Repair
and
Refinish



Sill ns

Dented

Over
30mm

Repair
and
Refinish



**Door
Mirror
Assy nsf**

Scratched
(Painted)

Over
25mm
Thru Paint

Smart
Repair



Wing nsf

Chipped
1 To 5

Smart
Repair

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Dented	With Paint Damage	Repair and Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing osf	Dented	Between 10mm + 30mm	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Chipped	1 To 5	Smart Repair
Badgedecal Rear	Missing	Replace	Replace
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Dented	Over 30mm	Repair and Refinish
Sill ns	Dented	Over 30mm	Repair and Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE Last Service - 14/10/2024 at 119,235 miles (10 SERVICES (4 MAIN DEALER))</p> <p>engine noisy and release bearing noisy/sticking</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>