

Vehicle Inspection Report

Date Inspected: 16/04/2025 08:46

Reg: GM68HLK

VIN: TMBKR7NE3K0117277

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	SKODA	Body Type	Estate	Doors	5
Model	OCTAVIA SE TSI S-A - 1498cc	Fuel Type	Petrol	Colour	Black
Mileage	59,395 miles	Transmission	Auto	Year of MFR	2019
				Date First Reg	25/01/2019

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	27/01/2026
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	3 mm	Tools	Yes
NSR Depth	4 mm	Spare	Steel

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No


History

Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bonnet

Chipped

1 To 5

Smart Repair

Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Front

Chipped

Multiple Chips

Smart Repair

Wing osf









Scratched

Over 25mm Not

Door osf

Scratched

Over 25mm Not

	Thru Paint Machine Polish		Screen Front Chipped UpTo 10mm Smart Repair	Thru Paint Machine Polish	
	Door osf Chipped 1 To 5 Smart Repair		Door osr Scratched Over 25mm Not Thru Paint Machine Polish		Door osr Chipped 1 To 5 Smart Repair
	Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish		Qtr Panel osr Chipped 1 To 5 Smart Repair		Bumper Rear Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Rear Scratched 25 to 100mm Thru Paint Smart Repair		Boot Lid Scratched Over 25mm Not Thru Paint Machine Polish		Qtr Panel nsr Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsr Scratched Over 25mm Thru Paint Refinish		Door nsf Dented With Paint Damage Repair and Refinish		Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair				

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D2
Dent/damage 30-100mm

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>