

### Vehicle Inspection Report

Date Inspected: 16/04/2025 10:53

**Reg:** BJ18VCW

**VIN:** SJNFAAF15U7434766

### NAMA Grading



Grade

**2**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	NISSAN	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	JUKE NISMO RS DIG- T - 1618cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	White
<b>Mileage</b>	60521 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2018
		<b>Gears</b>	6	<b>Date First Reg</b>	29/03/2018

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	4 mm	<b>Tools</b>	No
<b>NSR Depth</b>	4 mm	<b>Spare</b>	Inflation Kit

### Interior Condition

<b>Carpets</b>	Poor
<b>Upholstery</b>	Average
<b>Seats</b>	Poor
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No
<b>Comments</b>	drivers carpet holed

### Service History

<b>Service No</b>	
<b>History</b>	
<b>Stamps</b>	

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

### Damage Assessment



**Bonnet**  
Chipped  
1 To 5  
Smart Repair








**Bumper Front**  
Chipped  
Multiple Chips  
Smart Repair

**Bumper Front**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish

**Wing nsf**  
Scratched

**Door nsf**  
Scratched

	Over 25mm Not Thru Paint  Machine Polish		<b>Screen Front</b>  Chipped  UpTo 10mm  Smart Repair		Over 25mm Not Thru Paint  Machine Polish
	<b>Door nsf</b>  Chipped  1 To 5  Smart Repair		<b>Door nsr</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Door nsr</b>  Chipped  1 To 5  Smart Repair
	<b>Qtr Panel nsr</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Bumper Rear</b>  Scratched  25 to 100mm Thru Paint  Smart Repair		<b>Boot Lid</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish
	<b>Bumper Rear</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Carpets Front</b>  Holed  UpTo 3mm  Smart Repair		<b>Qtr Panel osr</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish
	<b>Door osr</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Door osr</b>  Chipped  1 To 5  Smart Repair		<b>Door osf</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish
	<b>Wing osf</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish		<b>Door nsf</b>  Dented  2 Or Less UpTo 10mm  Smart Repair		

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Carpets Front	Holed	UpTo 3mm	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Dented	2 Or Less UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**C2**  
Multiple Chips

Comments
<p>slight knocking noise</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>