



# VEHICLE INSPECTION REPORT

**LG16ZRF**

## Ford Ranger Limited 4x4 Dcb Td - 2198cc

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Photocopy



### Details

Reg. date	02/06/2016	Colour	Black	Number of stamps	7
Year	2016	VIN	6FPPXXMJ2PGR48002	Last service date	27/04/2023
Mileage	142,397 Miles Not Warranted	Service history	Yes	Last service miles	117,380
Fuel Type	Diesel	Service documents	Printout	Gearbox	AUTOMATIC

### NON-RUNNER

Last Service - 27.04.2023 at 117380 miles (7 services)

No V5

MOT Expired

Front bumper misaligned

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features


- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front armrest
- Rear headrests
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Telephone
- Digital radio
- Air conditioning
- Front electric windows
- Solid Paint
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear armrest
- 3x3 point rear seat belts
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Bonnet  
Chipped  
1 To 5



No Image



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Wheel nsf  
Corroded  
Light



6: Wing nsf  
Chipped  
Multiple Chips



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsf  
Scratched  
Over 50mm



11: Boot Lid  
Dented  
With Paint Damage



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Door osr  
Dented  
With Paint Damage






15: Wheel osr  
Scratched  
Over 50mm




16: Door osr  
Chipped  
1 To 5



17: Wing osf  
Scratched  
Over 25mm Not Thru Paint



18: Wing osf  
Rusted  
Over 5mm



19: Screen Front  
Chipped  
UpTo 10mm



20: Roof  
Chipped  
Multiple Chips

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK