

Vehicle Inspection Report

Date Inspected: 23/04/2025 16:31

Reg: LL17EEY

VIN: AHTHB3CD302121030

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	TOYOTA	Body Type	Pickup	Doors	5
Model	HILUX ICON D-4D 4WD DCB - 2393cc	Fuel Type	Diesel	Colour	Blue
Mileage	155,629 miles	Transmission	Manual	Year of MFR	2017
		Gears	6	Date First Reg	21/06/2017

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	7 mm	Alloys	Yes
NSF Depth	7 mm	Alloys That Need Refurb	4
OSR Depth	7 mm	Tools	No
NSR Depth	7 mm	Spare	Steel

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



















Boot Lid
Dented
With Paint Damage
Repair and Refinish

Qtr Panel nsr
Scratched
Over

Bumper Rear
Scratched
Over 25mm Not Thru Paint
Machine Polish

Bumper Rear
Chipped
Multiple Chips
Smart Repair

Door nsr
Scratched
Over 25mm Not

	25mm Not Thru Paint Machine Polish		Qtr Panel nsr Chipped 1 To 5 Smart Repair		Thru Paint Machine Polish
	Door nsr Chipped 1 To 5 Smart Repair		Door nsf Scratched Over 25mm Not Thru Paint Machine Polish		Door nsf Chipped 1 To 5 Smart Repair
	Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish		Wing nsf Chipped 1 To 5 Smart Repair		Bumper Front Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair		Bonnet Chipped 1 To 5 Smart Repair		Wing osf Chipped 1 To 5 Smart Repair
	Screen Front Chipped UpTo 10mm Smart Repair		Door osf Dented Between 10mm + 30mm Smart Repair		Door osr Scratched Over 25mm Not Thru Paint Machine Polish
	Door osr Chipped 1 To 5 Smart Repair		Qtr Panel osr Scratched Over 25mm Thru Paint Refinish		Roof Dented Between 10mm + 30mm Smart Repair
	Door nsr Dented Between 10mm + 30mm Smart		Door nsf Dented Between 10mm + 30mm Smart		Door osr Dented Between 10mm + 30mm Smart

Repair

Repair

Repair



**Door
Mirror
Assy nsf**


Broken

Needs
Replaced

Replace

Damage Lines

Component	Condition	Severity	Repair
Boot Lid	Dented	With Paint Damage	Repair and Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Roof	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsf	Dented	Between 10mm + 30mm	Smart Repair
Door osr	Dented	Between 10mm + 30mm	Smart Repair
Door Mirror Assy nsf	Broken	Replace	Replace



Splat Key

- S2**
Scratch/Paint defect 30-100mm
- S3**
Scratch/Paint defect 100m +
- D1**
Dent/damage under 30mm
- D3**
Dent/damage 100mm +
- C2**
Multiple Chips

Comments

missing both sill trims and slight vibration at idle

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.