

Vehicle Inspection Report

Date Inspected: 22/04/2025 12:56

Reg: YA61EWR

VIN: VF7PNCFB489605320

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	CITROEN	Body Type	Hatchback	Doors	5
Model	C1 VTR - 998cc	Fuel Type	Petrol	Colour	Black
Mileage	76,219 miles	Transmission	Manual	Year of MFR	2012
		Gears	5	Date First Reg	20/02/2012

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	No
NSF Depth	5 mm	Tools	Yes
OSR Depth	4 mm	Spare	Space Saver
NSR Depth	5 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No  
History  
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

## Damage Assessment



### Bumper Front

Scratched

25 to 100mm Thru Paint

Smart Repair

### Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish



### Bonnet

Chipped

1 To 5


Smart Repair



### Wing osf

Poor Previous Repair

Poor Paint Refinish



### Screen Front

Chipped

UpTo 10mm

Smart Repair



### Door osf

Dented

With Paint Damage

Repair and Refinish



### Door osr

Dented

With Paint Damage

Repair and Refinish



### Bumper Rear

Scratched

Over 100mm Thru Paint

Refinish



### Door nsr

Dented

With Paint Damage

Repair and Refinish



### Door nsf

Poor Previous Repair

Poor Paint Refinish



### Wing nsf


Poor Previous Repair

Poor Paint Refinish

## Damage Lines

Component	Condition	Severity	Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Poor Previous Repair	Poor Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Poor Previous Repair	Poor Paint	Refinish
Wing nsf	Poor Previous Repair	Poor Paint	Refinish

## Vehicle Splat



## Splat Key

- S3**  
Scratch/Paint defect 100m +
- D2**  
Dent/damage 30-100mm
- D3**  
Dent/damage 100mm +
- C2**  
Multiple Chips
- PP**  
Poor Previous

## Comments

noisy engine

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**