



VEHICLE INSPECTION REPORT

AU63NFH

Citroen Berlingo Multispace 1.6 e-HDi 90 Airdream VTR 5dr EGS6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	17/09/2013	Keys	2	CAP Clean	£2,175.00
Year	2013	Service history	Yes	CAP Average	£1,725.00
Mileage	114,888 Miles Warranted	Service documents	Service Book	CAP Below	£1,300.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	SEMI AUTO
Colour	BLUE	Last service date	15/09/2021	Gears	6
VIN	VF77J9HP8DJ770180	Last service miles	85,250		
Body Style	MPV	MOT Due	15/10/2025		

Last Service - 15.09.2021 at 85250 miles (7 services)

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	TOYO	2.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Audio remote control
- Air conditioning
- Front head restraints
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Fogdriving Lamp nsf
Broken
Replace



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Poor Previous Repair
Poor Paint

No Image

10: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




12: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint

No Image

13: Door osr
Scratched
Over 25mm Not Thru Paint

No Image

14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint

16: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK