

Vehicle Inspection Report

Date Inspected: 22/04/2025 10:57

Reg: YB72FMY

VIN: VXXUPHNEKN4431320

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	Hatchback	Doors	5
Model	CORSA ULTIMATE	Fuel Type	Petrol	Colour	Black
	TURBO - 1199cc	Transmission	Manual	Year of MFR	2023
Mileage	33,146 miles	Gears	6	Date First Reg	20/01/2023

Miscellaneous

V5 Location	No
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Inflation Kit

Interior Condition

Carpets
Upholstery
Seats
Parcel Shelf
Odour

Service History

Service Yes
History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No



Bonnet

Chipped
1 To 5
Smart
Repair

Wing osf

Scratched


Over
25mm Not
Thru Paint

Machine
Polish



Door osr

Chipped
1 To 5
Smart
Repair



**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair



**Bumper
Front**

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Door osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Rear**

Poor
Previous
Repair

Rippled
UpTo 30%

Repair
and
Refinish



**Qtr Panel
nsr**

Scratched

Over
25mm
Thru Paint

Refinish

Door nsr

Dented

Between
10mm +
30mm

Smart
Repair

Door nsf

Dented

Between
10mm +
30mm

Smart
Repair

Door nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsr

Chipped

1 To 5

Smart
Repair

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bumper Rear	Poor Previous Repair	Rippled UpTo 30%	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Dented	Between 10mm + 30mm	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

C2
Multiple Chips

PP
Poor Previous

Comments
£65 ADDITIONAL FEE Last Service - 09/12/2024 at 29,033 miles (2 MAIN DEALER SERVICES)
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.