

Vehicle Inspection Report

Date Inspected: 24/04/2025 14:20

Reg: HY64YRR

VIN: U5YHN516LFL153915

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	KIA	Body Type	Hatchback	Doors	5
Model	CEED 3 ECODYNAMICS CRDI - 1582cc	Fuel Type	Diesel	Colour	Silver
		Transmission	Manual	Year of MFR	2014
Mileage	93,007 miles	Gears	6	Date First Reg	30/09/2014

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	29/09/2025
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	Yes
NSR Depth	4 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No


Damage Assessment



Boot Lid
Chipped
Multiple Chips
Refinish



Bumper Rear Moulding
Broken
Needs Replaced
Replace



Bumper Rear
Scratched
Over 100mm Thru Paint
Refinish

Door nsr
Scratched
Over 25mm Not



Qtr Panel nsr
Scratched
Over 25mm
Thru Paint
Refinish

Thru Paint
Machine Polish



Door nsr
Dented
2 Or Less
UpTo 10mm
Smart Repair



Door nsf
Dented
Over 30mm
Repair and Refinish



Door Mirror Assy nsf
Scratched (Painted)
Over 25mm
Thru Paint
Smart Repair

Wing nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Wing nsf
Chipped 1 To 5
Smart Repair



Screen Front
Chipped
UpTo 10mm
Smart Repair



Bumper Front
Scratched
Over 100mm
Thru Paint
Refinish



Bonnet
Chipped
Multiple Chips
Refinish



Wing osf
Dented
With Paint Damage
Repair and Refinish



Door osf
Dented
With Paint Damage
Repair and Refinish



Door osr
Dented
With Paint Damage
Repair and Refinish



Qtr Panel osr
Dented
With Paint Damage
Repair and Refinish

Damage Lines			
Component	Condition	Severity	Repair
Boot Lid	Chipped	Multiple Chips	Refinish
Bumper Rear Moulding	Broken	Replace	Replace
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsf	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	Multiple Chips	Refinish
Wing osf	Dented	With Paint Damage	Repair and Refinish
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments
<p>£100 ADDITIONAL FEE SERVICES CONFIRMED BY MVS BLANDFORD LTD Last Service - 05/09/2023 at 76,291 mile</p> <p>.</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>