

Vehicle Inspection Report

Date Inspected: 29/04/2025 15:48

Reg: GU20VHV

VIN: WAUZZZGA6LA064815

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	AUDI	Body Type	Estate	Doors	5
Model	Q2 TECHNIK 30 TFSI - 999cc	Fuel Type	Petrol	Colour	Black
Mileage	33,199 miles	Transmission	Manual	Year of MFR	2020
		Gears	6	Date First Reg	31/07/2020

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	27/03/2026
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need Refurb	4
OSR Depth	6 mm	Tools	No
NSR Depth	6 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bumper Front

Scratched

25 to 100mm Thru Paint


Smart Repair

Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bonnet

Chipped

1 To 5

Smart Repair



Wing nsf
Chipped
1 To 5
Smart
Repair



Screen Front
Chipped
UpTo 10mm
Smart
Repair



Door nsf
Dented
With Paint
Damage
Repair
and
Refinish



Door nsr
Dented
Over 30mm
Repair
and
Refinish

Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint
Machine
Polish



Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart
Repair

Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart
Repair

Boot Lid
Scratched
Over 25mm Not Thru Paint
Machine
Polish

Qtr Panel osr
Scratched
Over 25mm Not Thru Paint
Machine
Polish



Door osr
Dented
With Paint
Damage
Repair
and
Refinish



Door osf
Dented
With Paint
Damage
Repair
and
Refinish



Wing osf
Scratched
Over 25mm Thru Paint
Refinish



Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint
Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Wing nsf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door nsf	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	With Paint Damage	Repair and Refinish
Door osf	Dented	With Paint Damage	Repair and Refinish
Wing osf	Scratched	Over 25mm Thru Paint	Refinish
Wing Front Arch Extension os	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D2
Dent/damage 30-100mm

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE EXPORTED 06/08/2021 Last Service - 28/03/2025 at 33,020 miles (1 MAIN DEALER SERV</p> <p>intermittent vibration</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>