

Vehicle Inspection Report

Date Inspected: 17/04/2025 15:36

Reg: NL14HSO

VIN: WAUZZZ8V7EA151286

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	AUDI	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	A3 SPORT TDI - 1968cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Grey
<b>Mileage</b>	135,203 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2014
		<b>Gears</b>	6	<b>Date First Reg</b>	24/03/2014

Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	26/06/2025
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	6 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	5 mm	<b>Tools</b>	Yes
<b>NSR Depth</b>	5 mm	<b>Spare</b>	Space Saver

Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

Service History

Service

Yes

History

Stamps

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Half Leather	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

Damage Assessment



Bonnet

Chipped

1 To 5

Smart Repair

Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Front

Chipped

Multiple Chips

Smart Repair

Wing osf


Scratched

Over 25mm Not

Door osf

Scratched

Over 25mm Not



**Screen Front**  
Chipped  
UpTo 10mm  
Smart Repair

Thru Paint  
Machine Polish

Thru Paint  
Machine Polish



**Door osf**  
Chipped  
1 To 5  
Smart Repair



**Door osr**  
Scratched  
Over 25mm  
Thru Paint  
Refinish

**Qtr Panel osr**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish

**Bumper Rear**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish



**Bumper Rear**  
Scratched  
25 to 100mm  
Thru Paint  
Smart Repair

**Boot Lid**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish

**Qtr Panel nsr**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish



**Door nsr**  
Dented  
2 Or Less  
UpTo 10mm  
Smart Repair

**Door nsf**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish

**Wing nsf**  
Scratched  
Over 25mm Not Thru Paint  
Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

Comments
<p>Last Service - 09/03/2019 at 76,408 miles (4 SERVICES (3 MAIN DEALER))</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>