



# VEHICLE INSPECTION REPORT

**YB12CYF**

## Mini Clubman 1.6 Cooper 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	18/06/2012	Keys	2	CAP Clean	£2,375.00
Year	2012	Service history	Yes	CAP Average	£1,925.00
Mileage	96,787 Miles Warranted	Service documents	Service Book	CAP Below	£1,475.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	SILVER	Last service date	07/02/2022	Gears	6
VIN	WMWZF320X0TY75019	Last service miles	58,510		
Body Style	Estate	MOT Due	09/02/2026		

£100 ADDITIONAL FEE Last service 07/02/2022 @ 58510 miles (2 SERVICES) Engine noisy and brake warning light on dash  
Drivers window fault

### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	SUNNY	Worn
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Not Thru Paint



2: Bumper Front Grill  
Broken  
Replace






3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm




5: Door nsf  
Chipped  
1 To 5



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Poor Previous Repair  
Rippled Over 30%





9: Boot Lid  
Dented  
Over 2 UpTo 10mm



10: Door osr  
Dented  
Over 2 UpTo 10mm




11: Door osf  
Dented  
Over 2 UpTo 10mm



12: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



13: Wheel osf  
Scratched  
Over 50mm



14: Tyre osr  
Worn  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK