

Vehicle Inspection Report

Date Inspected: 22/04/2025 12:22

Reg: EF61GWK

VIN: WF0UXXLTRUBJ13053

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	FORD	Body Type	Hatchback	Doors	3
Model	KA ZETEC - 1242cc	Fuel Type	Petrol	Colour	Silver
Mileage	89,920 miles	Transmission	Manual	Year of MFR	2011
		Gears	5	Date First Reg	22/12/2011

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bumper Front

Scratched

25 to 100mm Thru Paint

Smart Repair



Bonnet

Chipped

1 To 5


Smart Repair

Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish




Wing nsf

Dented

With Paint Damage

Repair and Refinish



Screen Front

Chipped

UpTo 10mm

Smart Repair



Door nsf

Dented

With Paint Damage

Repair and Refinish



Qtr Panel nsr

Dented

With Paint Damage

Repair and Refinish

Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Rear

Scratched

25 to 100mm Thru Paint

Smart Repair

Boot Lid

Scratched

Over 25mm Not Thru Paint

Machine Polish



Qtr Panel osr

Chipped

1 To 5

Smart Repair

Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door osf

Chipped

1 To 5

Smart Repair



Wing osf

Chipped

Multiple Chips

Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Dented	With Paint Damage	Repair and Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door nsf	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	Multiple Chips	Refinish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments
<p>noisy engine and drivers sun visor broken</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>