



VEHICLE INSPECTION REPORT

HJ12XTW

Skoda Yeti 1.6 TDI CR SE GreenLine II 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2012	Keys	1	CAP Average	£2,175.00
Year	2012	Service history	Yes	CAP Below	£1,725.00
Mileage	115,024 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	31/01/2018	Gears	5
Colour	BLUE	Last service miles	65,414	Doors	5
VIN	TMBKT75L2C6072377	MOT Due	09/04/2026		
Body Style	Hatchback	CAP Clean	£2,625.00		

£65 ADDITIONAL FEE Last service 31/01/2018 @ 65414 miles (4 MAIN DEALER SERVICES) EML light on Clutch pedal heavy

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Bonnet
Chipped
1 To 5



3: Wing nsf
Dented
Over 30mm



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Chipped
1 To 5



6: Door nsr
Poor Previous Repair
Poor Colour



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

No Image

9: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm

No Image

12: Door osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Rusted
UpTo 5mm

No Image

14: Wing osf
Scratched
Over 25mm Not Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Door Mirror Assy nsf
Broken
Replace



17: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK