

VEHICLE INSPECTION REPORT

DY66GXA

Vauxhall Astra 1.0T 12V ecoFLEX SRi 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	08/09/2016	Keys	1	CAP Clean	£2,525.00
Year	2016	Service history	Yes	CAP Average	£2,075.00
Mileage	95,243 Miles Warranted	Service documents	Service Book	CAP Below	£1,625.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	SILVER	Last service date	08/08/2024	Gears	5
VIN	W0LBF6EA2GG158481	Last service miles	89,832	Doors	5
Body Style	Hatchback	MOT Due	30/08/2025		

£100 ADDITIONAL FEE

Last Service - 08.08.2024 at 89832 miles (3 services) Clutch Replaced 31.10.2023 @ 83175 miles

Eml on

Tyres

NSF	MICHELIN	2.0mm	
NSR	KUMHO	OK	
OSF	BUDGET	2.0mm	_
OSR	BUDGET	3.0mm	
Spare			

Features

- Bluetooth connection
- Steering wheel mounted controls
 Electric door mirrors
 Audio remote control
 Air conditioning

- Front head restraints
 3x3 point rear seat belts
- Side airbagsAlloy wheels
- PAS
- Air conditioning
 Height adjustable drivers seat
 ABS

- · Central locking
- Rear parking sensorDigital radioClimate control


- · Rear headrests
- Isofix child seat anchor pointsRemote central locking
- · Rear wiper
- Body coloured bumpers
 Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Bumper Rear Scratched 25 to 100mm Thru Paint No Image

2: Boot Lid Scratched Over 25mm Not Thru Paint



3: Wheel nsr Scratched Over 50mm



4: Qtr Panel nsr Dented Over 2 UpTo 10mm



5: Door nsr Chipped Multiple Chips



6: Door nsf Chipped 1 To 5



7: Wing nsf Poor Previous Repair Poor Paint



8: Wheel nsf Scratched Over 50mm



9: Bonnet Chipped Multiple Chips



10: Bumper Front Cracked UpTo 25mm



11: Wheel osf Scratched Over 50mm



12: Door osf Chipped 1 To 5



13: Door osr Poor Previous Repair Poor Paint



14: Wheel osr Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK