

Vehicle Inspection Report

Date Inspected: 04/02/2025 09:57

Reg: T100EEL

VIN: JN1TENT30U0310711

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	NISSAN	Body Type	Estate	Doors	5
Model	X-TRAIL COLUMBIA	Fuel Type	Diesel	Colour	Blue
	DCI - 2184cc	Transmission	Manual	Year of MFR	2006
Mileage	134,526 miles	Gears	6	Date First Reg	31/05/2006

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	6 mm	Tools	No
NSR Depth	5 mm	Spare	Steel

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No
Comments	seats heavily stained

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bumper Front

Poor Previous Repair  
  
Paint Flake  
  
Refinish



Bonnet

Chipped  
  
1 To 5  
  
Smart Repair

Wing osf

Scratched  
  
Over 25mm Not Thru Paint  
  
Machine Polish

Door osf

Scratched



**Door Mirror Assy osf**

Scratched  
(Painted)

UpTo  
25mm  
Thru Paint

Smart  
Repair

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Door osf**

Chipped

1 To 5

Smart  
Repair



**Door osf**

Chipped

Edge Chip

Smart  
Repair



**Door osr**

Dented

With Paint  
Damage

Repair  
and  
Refinish



**Qtr Panel osr**

Rusted

Over 5mm

Refinish



**Bumper Rear**

Poor  
Previous  
Repair

Paint  
Flake

Refinish



**Boot Lid**

Dented

Over  
30mm

Repair  
and  
Refinish



**Qtr Panel nsr**

Dented

With Paint  
Damage


Repair  
and  
Refinish

**Door nsr**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Door nsr**

Scratched

UpTo  
25mm  
Thru Paint

Smart  
Repair

**Door nsf**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish



**Door nsf**

Chipped

1 To 5

Smart  
Repair

**Door Mirror Assy nsf**

Scratched  
(Painted)

Over  
25mm Not  
Thru Paint

Machine  
Polish

**Wing nsf**

Scratched

Over  
25mm Not  
Thru Paint

Machine  
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Poor Previous Repair	Paint Flake	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy osf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osf	Chipped	Edge Chip	Smart Repair
Door osr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Rusted	Over 5mm	Refinish
Bumper Rear	Poor Previous Repair	Paint Flake	Refinish
Boot Lid	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

**S1**  
Scratch/Paint defect to 30mm

**D2**  
Dent/damage 30-100mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

**PP**  
Poor Previous

**R**  
Rust

Comments
<p>vibration at idle and front bumper insecure</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>